
LEADJECK[®] CNC

聯傑自動化科技股份有限公司
LEADJECK AUTOMATION CO.,LTD.

台中市北屯區松竹路三段 51號
NO.51, SEC.3, SUNG CHU RD., TAICHUNG, TAIWAN, R.O.C.
TEL:886-4-2244-2421 FAX:04-2245-1598
E-mail:leadjeck@ms31.hinet.net Website:www.leadjeckcnc.com.tw

LEADJECK 2-Axes CNC Lathe Control

Page 1/7

A. CNC Lathe Control:

- .Type: LAC-50T/Plus
- .Controllable Axes: 2~5
- .Simultaneous Control Axes: 2~5
- .Spindle Axis: 1~2
- .Suitable machines: Flat Bed CNC Lathe, Slant Bed CNC Lathe, Heavy Duty Roll Lathe.
- .Extended Version: 3~12 Axes, with C-axis and Y-axis Turn-Mill Machines Tools.

B. Hardware Standard Feature:

- .15" High Resolution TFT LCD Color Monitor.
- .System with Milti-core in Parallel High Speed Processing.
- .Full Key Pad with Sealed Tack switch & LED Indicator.
- .Modular Hardware PC Boards for easy Maintenance.
- .PLC I/O Points with LED Indicator on System Relay Board for easy Trouble Shooting.
- .On-line Hardware Self-Diagnostic Function.
- .Healthy LED Indicator in each PC-boards and Fuses.
- .NC Part Programs, Control Software & System Parameters Stored in CF Memory Card for High Reliability, the Backup Battery is un-necessary.
- .Thru RS-232C, Portable CF Memory Card or Ethernet, System can be linked with PC Computer for High Speed On-line DNC Operation.
- .Thru Ethernet, System can be linked with Network for Remote Trouble Shooting and Update the Control Software.

C. Software Standard Feature:

- .Least Command Input: 0.001mm (Metric), 0.0001in (Inch).
- .G/M Code Compatible with FANUC System.
- .Tool Path with Z-X Graphic Display.
- .Graphic Display with Zoom In, Zoom Out and Shift Function.
- .Position of Relative, Work, Machine and All Coordinates Display.
- .PLC Input, Output and Internal Relay with Description and Status Display.
- .Alarm Messages with Full Description Display for easy Trouble Shooting.
- .NC Program G/M Code Instruction Display for easy Programming Debug.
- .PLC Ladder Capacity: 32 In, 32 Out, 256 Relays & 16 Timers and Counters.
- .System Parameters with Password Protection.
- .Working Time and Part Counter Display.
- .Cartesian Coordinates, Absolute/Incremental Programming.
- .Turning/Drilling Canned Cycle and Call Subprogram Functions.
- .ID/OD Chuck Clamp, Quill Interlock and Door Interlock.
- .Constant and Variable-lead Threading.
- .Turret Index and Tool Change control.
- .Tool Length in X,Z and Tool Nose Radius Compensation.
- .Imaginary Tool Nose Direction Number from 0 to 9.
- .12 Tool Length, Nose Radius and Direction Offset Parameters.
- .Spindle Jogging and Orientation.
- .Linear/Circular Chamfer Function.
- .Automatic Corner Feedrate Override.
- .Block Processing Time: 2ms.
- .Axes Auto Zero Return Function.
- .Hardware & Software Stroke Limit.
- .Position Loop with Feedforward and Linear or S-curve Acc./Dec. Control.
- .Actual Spindle Speed Control with S Code.
- .Axes Rapid Motion Backlash Compensations.
- .Axes Cutting Motion Backlash Acceleration Compensations.
- .Bi-directional Ball Screw Pitch Error Compensation.
- .Multi-Step Skip Function.
- .Feedrate Control Knob: 0% ~ 150%.

.Rapid Traverse Knob: 0%, 25%, 50% and 100%.

.Spindle Speed Control Knob: 50% ~ 120%.

.S Code and T codes with 4 Digits Programming.

.EIA or ISO Programming Code.

.Operation Mode: MEM, MDI, JOG, ZERO RETURN, EDIT and PROG LIST

.MEM and MDI Operation functions:

Block Delete, M01 Stop, Single Block, Dry Run, Simulation,
On-Line DNC, Re-Start, Auto Power Off and Handle Control Feedrate.

.JOG Mode Operation Functions:

Rapid Jog, Continuous Jog, Handle Jog, Chuck Inner, O.T. Release,
Chuck Clamp, Work Zero Set, Tool Offset Measure and Quill
Interlock.

.ZERO RETURN Mode Functions:

All Axes and Single Axis.

.Mid-Program Re-start:

The NC Program Can be Executed from the Start Block of any Tool' s
Command Group.

.Auto Power Off:

System Power can be Trun Off Automatically by M30 Code at the End
of NC Program.

.Handle Control Feedrate:

Feedrate can be Controlled by Swing the Electronic Handle, the Tool
Path Still follow the NC Program. Use this Function for easy Testing.

.Work Zero Setup:

The Zero of Work Coordinate can be Setup by Teach-in for Easy and
Safety.

.Tool Offset Measure:

The Tool Length Offset also can be Setup by Teach-in.

.Next Tool:

In JOG Mode, Key in the Number of Next Tool, and Press the “ Cycle
Start” Key, the Tool Changed Cycle will be executed.

D. G Code Functions:

- .G00: Rapid Motion.
- .G01: Linear Interpolation Motion.
- .G02: CW Interpolation Motion.
- .G03: CCW Interpolation Motion.
- .G04: Dwell, Exact Stop.
- .G09: Exact Stop.
- .G10: Set Offsets.
- .G20: Select Inches.
- .G21: Select Metric.
- .G27: Machine Zero Return Check.
- .G28: Return to Machine Zero.
- .G30: 2'nd Reference Point Return.
- .G31: Skip Function.
- .G32: Threading.
- .G34: Variable-Lead Threading.
- .G40: Tool Nose Radius Compensation Cancel.
- .G41: Tool Nose Radius Compensation Left.
- .G42: Tool Nose Radius Compensation Right.
- .G50: Coordinate & Max. Spindle Speed Setup.
- .G70: Finishing Canned Cycle.
- .G71: Stock Removal in Turning Canned Cycle.
- .G72: Stock Removal in Facing Canned Cycle.
- .G73: Pattern Repeating Canned Cycle.
- .G74: Peck Drilling on Z-axis Canned Cycle.
- .G75: Grooving on X-axis Canned Cycle.
- .G76: Multiple Threading Canned Cycle.
- .G90: Outer/Internal Diameter Cutting Cycle.
- .G92: Threading Cycle.
- .G94: End face Turning Cycle.
- .G96: Constant Surface Speed Enable.
- .G97: Constant Surface Speed Cancel.
- .G98: Feed Per Minute (mm/min., Inches/min.)
- .G99: Feed Per Revolution (mm/min., Inches/rev.)

E. M Code Functions:

- .M00: Stop Program.
- .M01: Optional Program Stop.
- .M02,M30: Program End.
- .M03: Spindle CW.
- .M04: Spindle CCW.
- .M05: Spindle Stop.
- .M08: Coolant On.
- .M09: Coolant Off.
- .M10: Chuck Clamp.
- .M11: Chuck Unclamp.
- .M12: Quill Out.
- .M13: Quill In.
- .M31: Change to High Gear.
- .M32: Change to Middle Gear.
- .M33: Change to Low Gear.
- .M97: Loop Operation.
- .M98: Call External Subprogram.
 - M98P__L__;
 - P: Subprogram Start Block N Code.
 - L: Cycle Times;
- .M99: End of External Subprogram.

F. Optional Functions:

- .Portable Electronic Handle.
- .The Spindle C Axis Control.
- .Dual System for Double Turret , Double Spindle Turn-mill Control.



*** 2-axes CNC Lathe ***



*** 3~5-axes CNC Machining Center ***



* Operation Panel in English *



* Operation Panel in Chinese *



* 12-axes CNC Controller *



* 4-axes CNC Controller *